

### THREE WEEK LOOK AHEAD SCHEDULE

From: March 20, 2011

To: April 09, 2013.

This three week look ahead schedule is an APPROXIMATION of how the work will progress. Minor changes to the 3WK LA are to be expected as the work progresses.

3/21/2011

Area / Activity Description	Resp.	Shift	Escort Req'd?	Week 1							Week 2							Week 3							Remarks
				Su	M	T	W	Th	F	Sa	Su	M	T	W	Th	F	Sa	Su	M	T	W	Th	F	Sa	
<b>Chiller Room</b>																									
Review and Approve Core Locations (Electrical)	LIN	1st	No																						
PIPE Hanger & Header Installation	IFW	1st	No																						
Install Electrical Conduit Hangers	LECO	2nd	No																						
Chiller Pad Layout	IFW	1st	No																						
VED Pad Layout	LECO	1st	No																						
Form Chiller & VFD Pads	CC	1st	No																						
Set/Install New Pumps incl. Trim Piping, etc.	IFW	1st	No																						
Pour Chiller & VFD Pads	CC	1st	No																						
Start Electrical Demolition / Escort / Rough-In in Tech Rm	LECO	2nd	No																						
(Install New Chillers	IFW	1st	No																						
<b>C1-1 Structure/Exterior Work</b>																									
Mobilize and Begin Installation/Driving of Mini-Piles	MT	1st	No																						
Form Mini-Pile Caps	CC	1st	No																						
Pour Mini-Pile Caps / Curing Time	CC	1st	No																						
<b>C1-2&amp;3 Structure &amp; Cooling Tower Work</b>																									
Rig / Install New C1-2&3 Structural Steel	VF	1st	No																						
Set New Cooling Towers # 2 & 3	VF	1st	No																						
(Install C1-3 Iron Piping, etc.	IFW	1st	No																						

**Schedule Legend:**

- = Escort Required / Lab Personnel Notification Recommended
- = Non-Sensitive Areas / No Escort Required